

Repairs from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

29198



LLOYD'S REGISTER OF SHIPPING

RUA BRÁS CUBAS, 3 - 9.º AND. - S/ 19

Caixa Postal 2039 - (Gonzaga)

Telefone: 2-8097 - SANTOS

8A

TELEGRAMAS: SURVEYOR - Santos

RECEIVED
20 JAN 1960

Santos, 9th January, 1960

The Secretary,
Lloyd's Register of Shipping
71, Fenchurch St.
London, E.C.3

Classn. (S) and (H)

"SÃO PAULO"

Dear Sir,

Further to my letter of the 19th December, 1959, your memo of 16th December, 1959, and your cable to Rio de Janeiro office, I am now informed by the Owners' representative that the vessel is to be withdrawn from class and that London office has already been advised of this.-

The vessel is now at this port of Santos and our services are not required on board.-

Attached herewith Owners' letter, and Rio de Janeiro Surveyors advised.-


La 12/1

Yours faithfully

Charles A. Davies
(Charles A. Davies)

2.59.

②



© 2021

Lloyd's Register
Foundation

Minute

Non-comp licence

Thursd 28th

Classing Co

011071-011078-0180

CLASSIFICATION

H
M

COPY TO FBD
COPY TO PUBS

SECRET



© 2021

Lloyd's Register
Foundation

Planning is drilled
Cables are repli
which is to be a