


4E

d by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor 13 OCT 1959

S NAME MOORLANDSLTR
REPORT OWNERS No. 28.7.58

The time taken to dry dock a vessel, draw and refit screwshaft, scrape + paint as necessary for dry docking + screwshaft surveys, varies from port to port and cannot be assessed from this office. This information could be easily obtained from the dockyard or repair yard where the survey will be held



29 JUL 1958



© 2021

Lloyd's Register
Foundation

011197-011206-0134