

Ship's name **LABUAN BAY**

Port **H.K.G.**

16 JUL 1963

No. 17839

Class is subject to main injection valve chest being renewed before the end of 4.64. Last survey date 28.6.63

The Surveyor reports propeller struck a lighter with engine running at half revolutions, on blade tip set back and fractured 6" from tip & another blade serrated, blade tips now dressed. The Surveyor recommends the tailshaft cone, propeller fastenings be specially examined & dealt with as necessary at next drydocking or not later than 10.63.

It is submitted that this vessel is eligible to remain as **CLASSED**. Subject as above & as now recommended.



© 2021

Lloyd's Register
Foundation

011227-011234-0304