

Oilfield

Formation in way of bridge not clear.

Plan of gangway to be submitted.

Wood core on forward hatch way on tank

Doors into tank side forward.

Ventilators (where shown) protected

Fuelling arrangements satis. battery



© 2021

Lloyd's Register
Foundation

011294-011303-01133