

WRECK
SECTION

15 JUN 1956

Received by Chief Ship Surveyor

GB

No.

Received from Chief Ship Surveyor

SHIP'S NAME

"SIEMISH "

REPORT

Lon.

No. 133666

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

The LONDON Surveyors report (4,56), ship examined in dry dock.

On account of damage due to collision temporary repairs, previously effected to bottom and side shell plating, etc. in way of Boiler Room, examined.

The Surveyors state that the ship is to be broken up. This information has already been received in London Office, and the Committee have given instructions for the Notation "Damaged by collision, 3,56 - to be broken up" to be inserted in the Register Book. Refer letter dated 24.5.56.



© 2021

Lloyd's Register
Foundation