

(Received at London Office

Insert Character by Shing and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to.....

Engineer Surveyor to Lloyd's Register of Shipping.

Port and starboard propellers blades faired and tips cleaned up. Shaft tapers cleaned up and propeller nuts repaired.

Docking Survey.

The vessel was placed in the Government Graving Dock.

The propellers and sea connections and fastenings were examined and found or placed in efficient condition.

The steering engine and windlass were examined and found in order.

S.R.L. items.

outer
Starboard/intermediate shaft not dealt with at this time.


"Endorsement"

Plugged tubes have now been dealt with and it is recommended that this item be deleted.

Boiler repairs.

The following repairs have now been dealt with:-

Forward Boiler. 11 plugged tubes renewed.)
(Please see Piraeus Report No.5940)
Aft Boiler. 14 plugged tubes renewed.)



© 2021

Lloyd's Register
Foundation