

4E

21 SEP 1956

l by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

S NAME "PONDAUNG"

REPORT

Adn.

No. 2243


DAMAGE to lubricating oil pipes.

Vessel at Aden awaiting towage to Burma.

A number of lubricating oil pipes missing and the Surveyor recommends the replace lubricating oil pipes and connections for the paddle wheel pedestal bearings and feathering gear be fitted on the ship's arrival at Rangoon to which port she is being towed.

IT IS SUBMITTED the vessel is eligible to remain AS CLASSED, subject as recommended.

Note. See footnote of endorsement dated 9.5.56.



© 2021

Lloyd's Register
Foundation

19.9.56.

011636-011645-0292