

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

40258 on the Wood, Iron or Steel of WESTSEE

TONNAGE: - Built at SUNDERLAND By whom W.M. DOXFORD & SONS LD. When 1924 10

GROSS 4408 Owners W. SCHUCHMANN Owners' Address

UNDER DK 4050 Managers Port belonging to BREMERHAVEN

NET 2619

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Capacity capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B. - All alterations in the existing records should be underlined.

Previous Report, No. 13504. Port Trieste

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER	Machinery and Boiler Surveys
100A1 with free board	LMC 9,50
4,51	PBS 9,50
ss Hpl. 10,46	TS CL 9,48
	OIL ENGINES

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

CONTINUOUS SURVEY

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Celling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Caulking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Coamings	Rudder	Scuppers	Boats
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained
" " In way of sidelights	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Bottom Plating	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
the Tanks been examined internally?		" " at other places	Rule length size
the Tanks been tested?		Stringers, Clamps & Shelves	Chain Locker
		Salting	Hawsers & Warps
		State if examined	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	10

FRI. 14 DEC 1951

Committee Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.

GENERAL COMMITTEE

Thursday, 3rd January, 1952.

Classing Committee's decision confirmed.