

3 FEB 1965

Ship's name "FREDRIKA"Port HAMNo. 14228Last survey date 10.12.64.Class is subject to

indented shell plates H.6 & 12 (pls.from aft), G.7 & 8,
J.4,5 & 14 (s.s.from aft) being specially examined and
dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~xxxxxxxx~~)Nature of present survey (afloat and in drydock)
~~XXXXXXXXXXXXXXXX~~


Damage - contact, involving side shell plating
in way of No.2 hold (s.s) - temporary repairs.

Recommendation SUBJECT as above and to indented shell plates in
2nd and 3rd strakes below sheerstrake in way of
No.2 hold (s.s) being specially examined and dealt
with as necessary next drydocking.

As Now Subject.

IN S.R.L.APPENDIX

(Main structure partly of P.403 Steel).



© 2021

Lloyd's Register
Foundation