

When handed in at Local Office..... 19

No. in
Reg. Book

First Survey. 3rd Nov. '52 Last Survey 9th November, 19 52.

By whom.....Vickers Armstrongs

When YEAR. 1943 MONTH 8

Name of Dock Mitsubishi, Kobe

Destined Voyage

Cell D Bor D Ba feet ; uE & B feet ; f feet
 tons. FPT tons ; APT tons ; MT feet tons.

erations in the existing records of tanks should be inserted.

All alterations in the existing records should be underlined.

Port, No. 699. Port Yka.

when held must be reported in detail and seriatim in the terms of the Rules and items remaining to complete
be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examination
Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to
and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the
Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form
and initials of any letters respecting this case.

where the Surveyor has not made a special damage report; he is required to state whether his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

EXAMINATION AS PER RULE FOR Docking & Condition.

:- Vessel placed in drydock on 3rd November, 1952, bottom and rudder cleaned examined re-coated. Undocked 9th November, 1952.

ks casings, coamings, ventilators, closing appliances, steering gear, windlass and equipments generally examined and found good. An annual load line survey was carried currently with the above and the report C 11(a) No. F1219 has already been forwarded as sly requested.

bottom bush found slack, recommended rudder to be lifted and bush renewed, after lifting
bottom gudgeon found scored, rebore. Pintle liner worn to be renewed.
bearing scored to be machined and liner fitted underneath bearing base.

carried out under Charterers A/c.

MAGE REPAIRS :—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :—
... ..								
Faired or Repaired								
Faired in place ...								

ON OF THE		Part examined		Good	
Good	"	Bulkheads	"	Engine Room Skylights	Good
"	"	Ceiling	"	Cargo Bunkers, Openings, Covers, &c.	"
"	"	Cement or Asphalt	"	Oil Bunkers	"
"	"	Rudder	Good	Scuppers	Good
Good	"	Steering gear and its connections	Good	Cargo Hatchways	"
ay of sidelights	Good	Windlass	"	Hatches	"
examined good	"	Have pumps been examined and found efficient?	No	Planking	"
"	"	Have Sluice Valves been examined and found efficient?	No	Caulking	"
"	"	Have Watertight Doors been examined and found efficient?	No	Treenails	"
"	"	Have Watertight Doors been examined and found efficient?	No	Breasthooks & Stemson	"
"	"	Have Ventilators and their Coamings been examined and found efficient?	Yes	Transoms, Pointers & Crutches	"
"	"	Air and Sounding Pipes	"	Timbers of Frame at openings	"
"	"	Doubling Plates under Sounding Pipes	"	" " at other places	"
amined internally?	No			Stringers, Clamps & Shelves	"
ested?	No			Salting	"

Copper, or Y.M.	
(State if on Felt.)	
When fitted, Month	Year
Boats	Good
Masts, Yards, &c.	"
Condition, how ascertained	from deck
(State if wedges removed.)	
Equipment letter	
Anchors, No. of	2B, 1S
Cables (State if now ranged)	
" length	mean diamr.
" (on board.)	15 FT. 11. SHORT
" Rule length	size
Chain Locker	"
Hawsers & Warps	Sufficient
Standing and Running Rigg	Efficient
Sails	"

servations, Opinion as to Class, Recommendation, &c.:

ly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon for example :— ".....to remain as classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of to remain as classed and to have record of survey, 1-38, and the notations of ss No. 1-38."

vessel, as far as now seen, is in good condition and eligible in my opinion to remain classed with fresh record of docking 11,52 subject as previously recommended.

Survey Fee (per Section 23) DOCKING \$ 15.00

Special Damage or Repair Fee (if any)
(per Sec. 23) 33 16 19

Travelling Expenses (if chargeable)

Second Surveyor's Fee ^{LATE} (if any)

Committee's Minutes

Character Assigned

Fees applied for,
A/c rendered from
London 7-194-54

Received by me, _____ 19____

Surveyor to Lloyd's Register of Shipping

TUESDAY - 4 MAY 1954

Record Laid up pending necessary repairs & surveys over.

Lloyd's Register
Foundation

No. 1 Hold H16 starb'd, Faired in place.

An Off Hire Survey was held on the 17th and 19th January, 1953 and a copy of the report is attached hereto.

Interim Certificate No.C-18298 issued, copy attached hereto.

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested & Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd																
	3rd "																
	Collective Weight																
	Stream																
	Kedge																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.



Lloyd's Register
Foundation