

RECEIVED

17 JUN 1960

Ans d. 17/6

CABLE IN

286 Recd 0900

17 JUN 1960

V

COMMITTEE LON

PO C AND W B12

TX3572 TMHA95 MONTEVIDEO 59/57 16 1528 VIA CW =

LT TELEX23405 COMMITTEE LONDON =

DREMAR REURCAR RECOMMENDED RENEWAL SIX SHELL PLATES EXTENSIVE
RENEWAL SHELL RIVETING SIXTEEN VENTS WITH COAMINGS REPAIRS DOORE E E E
REPAIRS DOORS GUARDRAILS STOP FEW MACHINERY ITEMS SEA VALVES
SCREW RUDDER EXAMINED FOUR SIDE TANKS TESTED NO TANK OR SPACE
OFFERED FOR INTERNAL EXAM OWNERS EFFECTED REPAIRS SHELL LEAKAGE
WITH DOUBLERS AND WELDED RIVETS VESSEL UNDOCKED SIXTEENTH =

SURVEYOR +

TELEX23405 +

2ND LINE PSE READ 2ND WORD SHELL ++

SENT 2108/16 DEF

COMMITTEE LON

012142-012147-0168

Lloyd's Register
Foundation

CLASSIFICATION

H
M

In Committee
17.6.60

In view of the circumstances of this case and the fact that the surveyor cannot recommend renewal of the Freeboard Certificate, it is submitted that the class might be exchanged.

[Signature]
17.6.60



© 2021

Lloyd's Register
Foundation