

DISCLOSED SECTION 550

Rpt. 8.

No. 550

(Received at London Office)

No. 123185

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of...

No. in Reg. Book. Survey held at... Date, First Survey... Last Survey... 19...

7108 on the Wood, Iron or Steel SS. 'Lin Kus' (No. of Visits...)

TONNAGE: Built at Quebec P.Q. By whom Morton Engineering & S.S. When 1945 MONTH 6

GROSS 2905 Owners China Merchants Steam Navigation Co. Ltd. (It not already recorded in Appendix to Register Book)

UNDER DK 2522 Managers... Port belonging to Shanghai

NET 1657 Managers... Port belonging to Shanghai

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...

Cell D Bor D Ba... feet; uE & B... feet; f... feet

total capacity... tons. FPT... tons; APT... tons; MT... feet tons.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 5008 Port Shi

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER	Machinery and Boiler Surveys
+100A1 8.48	+LMC 6.45 JS 7.48CL

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Surveys Delayed. Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE	
Decks	Bulkheads
Caulking of Decks	Ceiling
Coamings	Cement or Asphalt
Beams & Fastenings	Rudder
Outside Plating	Steering gear and its connections
" " in way of sidelights	Windlass
Frames	Have pumps been examined and found efficient?
Reverse Frames	Have Sluice Valves been examined and found efficient?
Longitudinals	Have Watertight Doors been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	Air and Sounding Pipes
Keelsons	Doubling Plates under Sounding Pipes
Stringers	
Inner Bottom Plating	
Have the Tanks been examined Internally?	
Have the Tanks been tested?	
Engine Room Skylights	
Coal Bunkers, Openings, Covers, &c.	
Oil Bunkers	
Scuppers	
Cargo Hatchways	
Hatches	
Planking	
Caulking	
Treenails	
Breasthooks & Stems	
Transoms, Pointers & Crutches	
Timbers of Frame at openings	
" " at other places	
Stringers, Clamps & Shelves	
Salting	
Copper, or Y.M.	
(State if on Felt.)	
When fitted, Month Year	
Boats	
Masts, Yards, &c.	
Condition, how ascertained	
(State if wedges removed.)	
Equipment letter	
Anchor, No. of	
Cables (State if new ranged)	
" length mean diamr.	
(on board.)	
" Rule length size	
Chain Locker	
Hawsers & Warps	
Standing and Running Rigging	
Sails	

General Observations, Opinion as to Class, Recommendation, &c. : State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	Special Damage or Repair Fee (if any) (per Sec. 23)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for,	Received by me,
£	£	£	£	10	10

Committee's Minute... Character Assigned... Red Line... THURS 14 FEB 1952... Surveyor to Lloyd's Register of Shipping... GENERAL COMMITTEE... Thursday 6 March 1952... Classing Committee's decision confirmed.

3001 L/10. Transfer Ink. (MADE AND PRINTED IN ENGLAND.)

Is Certificate required? If so, to be sent to