

4E

25 NOV 1955

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME

"SANTO"

REPORT

Osl.

No. 7833

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This vessel has a notation of "Laid Up Surveys Overdue".

Docking. Screw shaft drawn, found cracked and now changed. On completion, the shafting was found out of alignment and a recommendation was made that this be corrected. The Owners have since stated that the machinery has been removed and that they no longer require the Society's Classification. The Modified Survey of the machinery, due 12.52, and Special Survey, due 12.54, have not been held.

The case is submitted for the consideration of the Committee.



Lloyd's Register
Foundation

012246 - 012255 - 0021 23.11.55.