

Ship's Name ~~SS/MS~~ "DAWNLIGHT I"

LR. 651537

Port of
Registry GREENOCK

Port GREENOCK

Date of build 6-1965 Is there a Rpt. 9? Yes

Rpt. No. 27890

No. of visits 2

First date 18.3.66

Last date 21.3.66

Interim Cert. issued
& copy herewith? YesDamage rpt. issued
& copy herewith? No

Last rpt. (H.Q. only) GRK 27750

Date of
completing rpt. 4.4.66

Surveyed at, if different from Port above -

Surveyed afloat
and/or in D.D. Drydock

Last date of examination in D.D. 21.3.66

Has a Load Line
Survey been held? No

Summer freeboard as verified -

State which additional Rpt. 8 is attached: (CANN) (PS); (DRY) (EQ) (PK)

Survey fees

Damage fee

Expenses -

Docking £2.18. 0.

£2. 2. 0.

S.A. fee -

I have surveyed the above-named ship in accordance with the Rules for DOCKING AND DAMAGE

Damage stated to have been caused by collision with the M.S. "LOCHIEL"
at Port Ellen on the 27th November, 1965:-NOW FOUND:- Shell plate F.2 (p.s.a.) indented.NOW DONE FOR REPAIRS:- Shell plate faired in place.CONDITIONS OF CLASS (S.R.L. NO.249) NILS.R.L. APPENDIX NO.17:- NIL

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with/without fresh record of dry docking 3,66 subject to any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee GLASGOW

26 APR 1966

Minute DS 3, 66

Th. Linthorpe
Surveyor to Lloyd's Register of ShippingDF (FE)
ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

012246-012255-0R334

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name **SS/MS** "DAWNLIGHT I"
LR. 651537

S.S. () Due

Port GREENOCK

Rpt. No. 27890

	<u>Examined & condition</u>		<u>Examined & condition</u>
In dry dock from	18.3.66	* Air & sounding pipes	Above deck - Good
" " " to	22.3.66	Doublers under " "	Not examined
Shell plating	Yes - Good	Steering arrangements (main)	Yes - Good
Sternframe	" "	" " (aux)	" "
Rudder	" "	Windlass	" "
Was rudder lifted?	No	Masts & rigging	" "
Plating, etc. in way of shell openings	Yes - Good	Hand pumps & suction	Not examined
Side scuttles & deadlights	Not examined	W.T. doors	" "
Overbd. scuppers & discharges	" "	Bulwarks, freeing ports, etc.	Yes - Good
F.P. spaces	" "	Summer freeboard as verified	-
Chain locker	" "		
A.P. spaces	" "		
Engine space	" "		
Boiler space	None	<u>EQUIPMENT:</u>	
Under E. & B.	Not examined	Equipment letter	b
Coal bunker	None	Fee ltr., if diff. from eqpt. ltr.	
Tunnel & well	Not examined	Anchors: No. on board	1B 1K 1S
Cement, asphalt, etc., on btm. shell	" "	State if ranged	No
Weather decks	Yes - Good	Length on board	Stated
* Casings	" "	Mean dias. range from	Complete to
* Deckhouses	" "	Rule length	Dia.
* Superstructures	" "	Mooring ropes	Yes - Good
* Skylights	" "		
* Companionways	" "		
* Hatchways	" "		
* Ventilators	" "		
Other items:	Not examined		

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

Thimothée
 Surveyor to Lloyd's Register of Shipping

Foundation

012246-012255-0233 1/2

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	Yes - Good	F.P. tank		
"	'Tween decks	None	A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
"	'Tween decks				
No. 3	Hold		O.F. bunkers		
"	'Tween decks				
			Settling tanks		
No. 4	Hold				
"	'Tween decks		Deep tanks		
No. 5	Hold				
"	'Tween decks		Side tanks		
No. 6	Hold		Wing tanks		
"	'Tween decks				
			Other tanks:		
	Cargo battens	None			
	Ceiling, etc.	Yes - Good			

NONE

NOT EXAMINED



© 2021

Lloyd's Register
Foundation