

The class is subject to the repaired saturated steam steel pipe between boiler and Port Superheater header being renewed or efficiently repaired at the earliest opportunity and in any case before the end of 8:59.

21 OCT 1959

4E

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

P'S NAME GUDMUNDUR JUNI

REPORT

RJK

No. 3286

M.B.S. due 7:59 now held

Docking.

S.R.L. This item now dealt with and the

Surveyor recommends its deletion

It is noted that the main and auxiliary machinery has been generally examined including the electrical. It is however observed that a megger test of the electrical circuit has not been carried out as required by Circular 14959 and the Surveyor should be so advised. It is submitted that in this instance it may be accepted for six months elapsement.

It is submitted that this vessel is eligible for THE RECORD. M.B.S. 8:59

without Special Condition

Lf 20/10/59

012377-012385-0175