

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

21st April, 1964

Dear Sirs,

s.s. "LANTAO"

When this ship was at Port Said last month it was reported that shell plating in way of frame 121 in 3rd strake below sheerstrake and frame 135 in 2nd strake below sheerstrake was fractured.

Temporary repairs were effected at that time but it has been recommended that permanent repairs be effected on the completion of the ship's present voyage and not later than the end of next month. Meanwhile, class has been continued subject, *inter alia*, to this matter receiving attention by that time.

I shall be glad to know what early arrangements have been made for the Main Boiler Survey, due in October last, to be held.

Yours faithfully,

c.c. Hkg

pro Clerk to the
Classification Committee

Messrs. Pan Norse Steamship Co. S.A.,
c/o Waller & Co. Ltd.,
Hong Kong & Shanghai Bank Building,
Post Box 40,
Victoria,
HONG KONG



© 2021

Lloyd's Register
Foundation

012711-012715-0025