

EA

17 APR 1964

Ship's name "LANTAO"

Port

P.SD

No. 7330

Last survey date 29.3.64.

Class is subject to

bottom shell plates B.2 and C.1 (p.s.f)^{BEING SPECIALLY EXAMINED & DEALT WITH AS NECESSARY} and shell plating in 2nd strake below sheerstrake in way of No.5 hold (s.s) being permanently repaired next drydocking. ACTION is DEFERRED for examination in drydock after grounding.

S.R.L. Appendix (as before ~~XXXXXX~~)

Nature of present survey (afloat ~~and in drydock~~)

Temporary repairs to fractured shell plating.

Recommendation

SUBJECT as above and to fractured shell plating (s.s) in way of frame 121 in 3rd strake below sheerstrake and frame 135 in 2nd strake below sheer being specially examined and permanently repaired on completion of present voyage and not later than 5,64, but further ACTION continue to be DEFERRED for examination in drydock after grounding.

SUBJECT.


IN S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX.

Indented shell plating (s.s.f)

also shell plates C.3 and D.6 (p.s.f).



© 2021

C.S.S. Records Dept.
to note.

Lloyd's Register
Foundation

CBM.
17.4.64