

20 MAR 1964

Ship's name "LANTAO"

Port Cbo

No. 5538

GB

Class is subject to bottom shell plates B.2 & C.1 (p.s.f) being specially examined and dealt with as necessary next drydocking. Last survey date 8.1.64.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Nature of present survey (afloat ~~and in drydock~~ ~~XXXXXXXXXXXXXXXXXX~~)


Temporary repairs to wasted shell plate in way of No.5 hold(ss)

Recommendation

SUBJECT as above, and to shell plating in 2nd strake below sheerstrake in way of No.5 hold (s.s) being permanently repaired next drydocking.

As Now. Subject /  
IN S.R.L. APPENDIX.

Indented shell plating (s.s.f)  
also shell plates C.3 & D.6 (p.s.f).



© 2021

Lloyd's Register  
Foundation

*SSK*  
*20/3/64*