

EA

9- MAY 1963

Ship's name

"PADERWSKI"

Port

NTS

No.

963

Last survey date

4.4.63.

Class is subject to

15 fathoms of chain cable being supplied at the earliest opportunity and to defective side shell rivets in lower strakes in way of after end of No.2 hold (s.s) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~ or none)

Nature of present survey (afloat and ~~XXXX DRYDOCKXX~~)

Temporary repairs to ice damage.

Recommendation

SUBJECT as above and to defective rivets in shell plating in 4th and 5th strakes below sheer in way of No.4 hold (p & s) being specially examined and dealt with as necessary next drydocking.

As Now Subject

~~IN S.R.L.APPENDIX~~

~~(Main structure partly of P.5 Steel).~~



f.c
9/5/63