

EA

COPY

Ship's name "PADERWSKI" Port NTS No. 963  
Last survey date 4.4.63.

Class is subject to

15 fathoms of chain cable being supplied at the earliest opportunity and to defective side shell rivets in lower strakes in way of after end of No.2 hold (s.s) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before or none)x

Nature of present survey (afloat and in drydock)

Temporary repairs to ice damage.

Recommendation

SUBJECT as above and to defective rivets in shell plating in 4th and 5th strakes below sheer in way of No.4 hold (p & s) being specially examined and dealt with as necessary next drydocking.

As Now Subject

~~IN S.R.L. APPENDIX~~  
(Main structure partly of P.5 Steel).

End. S.1

Minute



© 2021

Lloyd's Register  
Foundation

012 796-012800-0126