

Ship's Name ~~SSMS~~ " PADEREWSKI " 7230 Gross tons

Is there a rpt. 9? Yes (9A & 9B) Port BORDEAUX Rpt. No. 7089
No. of visits 13 First date 8th Oct. Last date 19th Oct. 62

Interim Cert. issued & copy herewith? Yes. Damage rpt. issued & copy herewith? - Last rpt. (H.Q. only)

Date of completing rpt. 2/11/62 Surveyed at, if different from Port above

Surveyed afloat and/or in D.D. Afloat. Last date of examination in D.D. -

Has a Load Line Survey been held? No. Freeboard Marks verified -

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees - Damage fee NF. 655,00 Expenses NF. 150,00

S.A. fee

I have surveyed the above ship in accordance with the Rules for Damage to the Engine Room Sea Chest in No. 6 Double Bottom Tank, port side.
(Leakage having been noted in the No. 6 D.B. Oil Tank).

./.....

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

I recommend that this ship remain as classed ~~with~~ /without fresh record of ~~dry docking~~ survey.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

MONDAY 26 NOV 1962

Minute

As now subject
ABS 10. 62
Note Bdx subject

Surveyor to Lloyd's Register of Shipping



Lloyd's Register Foundation

012796 - 012800 - 0130

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

recommended should be
r "defects & repairs".
as been subjected to
pressure test this should be stated.

4088 Bdx.

[Handwritten signature]

[Handwritten initials]

[Handwritten mark]

[Handwritten mark]

./.....

Now done :-

- Sea chest box, port side, was obturated externally by a Diver and it was then possible to enter into the box to carry out repairs.

Please refer to attached Plan No. 1361.1 for damage and repairs.

On completion of the repairs testing were carried out with satisfactory results.

CSSR

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					



© 2021

Lloyd's Register
Foundation

This Certificat
"While the
understood that
inaccuracy in any
or for any error
of the Society."

Cert. B 80m, 4.62