

13 MAR 1962

ed by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

P'S NAME .....

"P R A M B A N A N"

REPORT .....

SBA  
L.A.

6439

No. 16382

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

This ship was built in 1946-4 and a Special Survey (C) becomes due in 2,63.

This ship is subject to keel plates Nos.6,7 & 8 and 'A' strakes plates Nos.8 & 9 (p.s) with structure in way being specially examined and dealt with as necessary next drydocking.

There is an S.R.L.Appendix item.

The SOURABAYA Surveyors report (1,62) ship examined in dry dock and temporary repairs effected to wasted bottom and side shell plating. They further state that the ship will be re-drydocked on her arrival at Djakarta from present voyage.

In a letter dated 14.2.62 the Djakarta Surveyors report that they have been advised by the new Owners of this ship that they no longer desire Classification with the Society.

In view of the above, it is submitted the Notation "Class Withdrawn - Reported defects" be inserted in the Register Book Supplement.

16  
3  
16

INSERT IN R.B. SUPPLEMENT.

"Class Withdrawn - Reported defects".

IN S.R.L.APPENDIX.

Bottom plating (p & s) slightly wavy.

5.3.62.



© 2021

Lloyd's Register  
Foundation

012966-012982-0113