

The class is subject to the main engine No. 1 cylinder jacket being further examined by 1.59.

15 JAN 1959 4E

by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

NAME..... PORT WAIKATO..... REPORT..... Lyt..... No. 4457.....

Damage to main engine No. 1 cylinder, No. 1 cylinder cover and No. 1 piston, gudgeon pin and bush repaired and No. 1 cylinder found leaking, slightly where previously Metalock repaired. Cylinder now repaired by fitted copper patch and the Surveyor recommends main engine No. 1 cylinder be renewed at the earliest opportunity and by 11.59

IT IS SUBMITTED that this vessel is eligible to remain as CLASSED, subject as now recommended.



© 2021
19.12.58

Lloyd's Register
Foundation

013057-013062-0232