

M.S. "HOEGH SILVERSTAR".

It is submitted the Copenhagen Surveyors be informed that the class of this vessel was withdrawn from the Society's Register Book by the General Committee on the 29th ultimo.

A Report was, however, received from the Vancouver Surveyor, dated 1st August, in which he refers to the condition of the stern frame. He states that he found it badly corroded and showing numerous surface cracks. These cracks were veed out and repaired by electric welding. Other repairs were done, but there is no indication in this Office that the Surveyor in conjunction with the Surveyor to the Norske Veritas rejected the stern frame.

[Handwritten signature]
28. 10. 38. *[Handwritten initials]*

Vancouver Surveyors reported they first numerous surface cracks & corrosion in stern frame these repaired by electric welding & surveyors recommended lower half further examined or renewed next dry docking stop no further report received stop vessel withdrawn from class 29th ult.