

SHIP'S NAME "CAMPERO"

PORT BCL

No. 8329

LAST SURVEY DATE 1.9.65.

CLASS IS SUBJECT TO :-

1. Port main engine Nos. 1, 3 & 4 and starboard main engine Nos. 1, 2 & 3 crankpins (cracks) ground out 4.65) being crack-detected and shafts alignment checked by 7.65 (3 months).
2. Starboard main engine crankshaft being renewed by 1.66 (9 months).
3. Starboard auxiliary engine bedplate (M.L. 4.65) be examined by 10.65 (6 months).

SRH — Subject item 1 — Port ME Nos 1, 3 & 4 crankpins examined & crack detected in way of ground out cracks — no evidence of cracks found & Surveyor now recommends that Port ME Nos 1, 3 & 4 crankpins be specially examined & crankshaft alignment checked by 1.66.

Surveyor reports that the Starboard ME Nos 1, 2 & 3 crankpins were not available for examination; the crankpin bearings

013671-013677-0005 1/3

SHIP'S NAME

PORT

No.

LAST SURVEY DATE

CLASS IS SUBJECT TO

having been re-assembled after an examination
by the National Authority Surveyors.

SRL - Subject item 3 not dealt with.

It is submitted that
this vessel is eligible to
remain as **CLASSED**

R.L. 12
10
05.

subject to 1 - Port ME No 1,324 crankpins being
crack detected & crankshaft alignment
being checked by 1.66.

2 - Starboard ME No 1,223 crankpins being
crack detected & crankshaft
alignment being checked by 7.65.

3. Starboard ME crankshaft being
inspected by 1.66 (9 mos)

R.L.

0005 2/3

SHIP'S NAME

PORT

No.

LAST SURVEY DATE

CLASS IS SUBJECT TO

4 Starboard Aux. engine bedplate (M/L 4.65)
being examined by 10.65 (6 mos).

20.5

0005 3/8



© 2021

Lloyd's Register
Foundation