

10 AUG 1973

A02

Ship's Name SSMS "MOANA ROA"

Gross tons 2893

1 L.R. number 7
5 2 3 7 9 6 9

8 Port 10
A U K

11 Report No. 16
3 0 0 2 7 6

Recommended survey
17 date 20

30 AUG 1973

First date 31-7-73

Last date 31-7-73

Port of Registry Auckland

Date of build 1960-8

FEES	
Part E.S. (Reclassification Survey)	\$32.50
EXPENSES	
	\$0.75 S.A.

Damage report issued with copy herewith?	No	No. of visits	1
--	----	---------------	---

Surveyed at, if different from port above. -

Last report (HQ only)

Total No. of items Coded overleaf	35	37	38	TOTAL FEES and EXPENSES	49
				33.25	

I recommended that the machinery of this ship be reclassified with +IMC 7/72 (as previously recommended) when the Reclassification Survey has been completed.

~~Subject to the following conditions of class detailed below and/or as previously recommended.~~

[Particulars of defects, repairs, alterations, etc., and reasons for conditions of class on Rpt. 9(A) or (contd)]

I declare that the items detailed in this report (except as stated otherwise) comply with the requirements of the Merchant Shipping (Cargo Ship Construction and Survey) Rules 1965, applicable to this ship, and are in all respects satisfactory for the service on which the ship is intended to ply namely International voyages within the limits.

Recommendation confirmed (subject as per endt.)

(The above declaration applies only to sea-going cargo ships of 500 tons gross and above registered in the U.K.)

D.F. Edwards
Surveyor to Lloyd's Register of Shipping
D.F. Edwards.

1st August 1973
Date

Woy
28/8/73

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above)

Date of Committee

MONDAY 10 SEP 1973

Minute

Deferred for comp Reclass
013884 - 013889 - 0026

FOR CHAIRMAN
CLASSN. ETEE

Posting

SRL

TRO

Header

Certs

scribed fully under "defects and repairs". When any part has been hydraulically tested the survey should be stated.

numbers. Where re-examination or repairs should be made before that date a distinguishing mark thus + should be inserted against the item and the circumstances and action taken or recommended de-

Items examined and found or placed in good condition, and considered to be acceptable until the date of the next Periodical examination, should be entered on the reverse together with the appropriate code



Punch
Verify

13-07

Items SEEN at this survey		Code number		
1	Port Main Engine Thrust Block and Bearing	17		
2		21		
3		25		
4		29		
5		33		
6		37		
7		41		
8		45		
9		49		
10		53		
11		57		
12		61		
13		65		
14		69		
15		17		
16		21		
17		25		
18		29		
19		33		
20		37		
21		41		
L i n e	Items other than CSM, or, ES examined in a different month from that shown overleaf	Date examined		Code number
		Month	Year	
1		17		
2		25		
3		33		
4		41		

78 79 80
A03

78 79 80
A03

78 79 80
A04

Condition of oil gland and/or sternbush clearance { portmm beforemm aftermm
 stb'd.....mm If relined state clearance beforemm aftermm

