

2m.7.44.

t to Chief Surveyors.....

Received from Chief Surveyors. 30 JAN 1945

SHIP'S NAME "EMPIRE WILSON" REPORT *56* No. 69090A

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey *Docking, Damage & Temp Rps.* When due.....

Subject to slightly buckled shell plates H4 & 5 etc. (p.s.) and slightly buckled upper deck beams in No. 5 'tween decks (p. & s.) being permanently dealt with at Owners' convenience, to cargo ballers being fitted at the first opportunity and (a bower anchor & 60 fathoms of chain cable being supplied).

f.c.D.
22.1.45 *Esth.*



© 2021

Lloyd's Register
Foundation

010451-014462-0228