


0  
COMMITTEE LDN  
OSEAGRAM 21 LN

CABLE IN



TX338 SNA18/A30 SANTOS 17 29 1129 LT =

30 DEC 1964

649

LT =  
COMMITTEE LONDONEC3 =

LUCIANO CASTRO NOW DOCKED FOR PERMANENT  
BOTTOM REPAIR ADVISE OUTSTANDING REQUIREMENTS  
FOR RECLASSING =  
SURVEYOR +

COL LONDONEC3  
SENT 0045/30 AAR

OSEAGRAM 21 LN  
COMMITTEE LDN



© 2021

Lloyd's Register  
Foundation

014835-014842-0223

SR/ER

REPORTS

4/13

For reinstatement of class  
and notation of SS 4, 64 the anchors to  
chain cables and chain locker remains to  
be examined and indented bottom shell plating  
etc. in way of nos. 1, 2 & 3 A.B. tanks (P+S) to be  
dealt with as necessary. All double bottom tanks to be  
tested on completion of repairs.

30/12/64

See report sheet for working  
sub



© 2021

Lloyd's Register  
Foundation