

COMMITTEE LDN
OSEAGRAM 01 LN

26 FEB 1964

TX214 TNA80/110157
RIODEJANEIRO 32 25 1830

CABLE IN

Ansd

754

26 FEB 1964

LT
COMMITTEE LONDONEC3

LUCIANO CASTRO IN DRYDOCK WITH BROKEN SCREWSHAFT STOP PLEASE
CABLE ORIGINAL STERNTUBE ARRANGEMENT STOP VESSEL NOW FITTED
WOOD AFTER BUSH UNKNOWN OIL GLAND ARRANGEMENT STOP WOULD
APPRECIATE DRAWING
THIRLAWAY

COL LONDONEC3

OSEAGRAM 01 LN
SENT 2358 WMF
COMMITTEE LDN

*Drawings not available but
original arrangement was screw-
shaft running on cast iron with
cederwall oil gland stop Refer your
report August 1962 for remetalting of
bush*

R 26/2/64

DF

014835-014842-0252

ER

REPORTS

M

Cable sent 26.2.64

~~WIRE REQUESTED~~

~~In original arrangement
screwball ran in cast iron bush
without white metal lining and bedrock
ground adjustable No. 5 was fitted. Stop
Drawing follow
Forward by air mail the two drawings
& the dimension table~~

R 26/2/64



© 2021

Lloyd's Register
Foundation