

COPY

EA

Ship's name

"INTERPRETER"

Port

AMS

No. 25274Last survey date 25.2.63

Class is subject to indented side shell plating etc. in 2nd and 3rd strakes below sheer in way of deep tank (s.s) forward bulkhead being specially examined and dealt with as necessary, to fore-castle sheerstrake plate (p.s.f) etc. being permanently repaired and to indented shell plate No.4 from aft in main sheer (p.s) and structure in way and indented shell plates Nos.13 & 14 (from fwd) in 2nd below sheerstrake (p.s) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~or none~~) with as necessary next drydocking. ACTION is DEFERRED for completion of S.S. By 1.63.

Surveys due

SPECIAL SURVEY (C) due 1.62 - commenced Liv.5.62 and subsequently advanced. Postponement until 1.63 approved 15.3.62.

Nature of present survey (afloat and in drydock)

Docking: Spécial Survey

Permanent repairs to damage - various causes, including S.R.L. and S.R.L. Appendix items.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

Wed on
Jan 1

SS proposed to ~~be~~ completed by ~~XX~~Recommendation

SUBMITTED record of DS 2.63 and Notation of SS 2.63 be assigned, without special conditions.

DS 2.63

SS 2.63 Without.

DELETE S.R.L. APPENDIX.

© 2021

Lloyd's Register
Foundation