

Rpt. 8

## REPORT OF SHIP SURVEYS AND REPAIRS

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Received London

-4. AUG. 1965

Ship's Name ~~SS~~/MS "INTERPRETER" LR 516201  
 Gross tons 6815 Port of Registry Liverpool Port Liverpool  
 Date of build 1948 5 Is there a Rpt. 9? *yes* Rpt. No. 166681  
 No. of visits One First date and Last date 30/6/65  
 Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) *LON. 153705*  
 Date of completing rpt. 30/6/65 Surveyed at, if different from Port above -  
 Surveyed afloat and/or in D.D. Dry Dock Last date of examination in D.D. 30/6/65  
 Has a Load Line Survey been held? No Summer freeboard as verified -

*epm* State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees

Damage fee

Expenses

Dky £10

Rpt £5

S.A. fee

30.

I have surveyed the above-named ship in accordance with the Rules for Docking Survey.

Repairs Wear and Tear : Rudder side plating (SS) fractured at slot weld - cut out and rewelded.

Several rivets in shell plate ~~F9~~ (PS) leaking - rivets now caulked tight.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with ~~without~~ fresh record of dry docking 6,65 subject to any condition at present attached to the ship's class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

LIVERPOOL - 3 AUG 1965

J. D. Sutherst.

Minute

DS 6,65

Surveyor to Lloyd's Register of Shipping

ALSO FOR



SRL

POSTING

HEADER

CERT



PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					



© 2021

Lloyd's Register  
Foundation



## Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name ~~SS~~/MS "INTERPRETER"

Port Liverpool

S.S. ( ) Due

Rpt. No. 166681

In dry dock from 28/6/65

In dry dock to 30/6/65

<u>Examined &amp; condition</u>		<u>Examined &amp; condition</u>	
Shell plating	Good	* Air & sounding pipes	Not examined
Sternframe	Good	Doublers under " "	Not examined
Rudder	Good	Steering arrangements (main)	Good
Was rudder lifted?	No	" " (aux)	Good
Plating, etc. in way of shell openings	Good	Windlass	Good
Side scuttles & deadlights	Not examined	Masts & standing rigging	Not examined
Overbd. scuppers & discharges	Good	Hand pumps & suction	Not examined
F.P. spaces	Not examined	W.T. doors	Not examined
Chain locker	Not examined	Bulwarks, freeing ports, etc.	Good
A.P. spaces	Not examined		
Engine space	Not examined		
Boiler space	Not examined		
Under E. & B.	Not examined		
Coal bunker	Not examined	<u>EQUIPMENT:</u>	Not examined
Tunnel & well	Not examined	Equipment letter	
Cement, asphalt, etc., on btm. shell	Not examined	Fee ltr., if diff. from eqpt. ltr.	
Weather decks	Good	Anchors: No. on board	
* Casings	Not examined	Cables {	State if ranged
* Deckhouses	Not examined		Length on board
* Superstructures	Not examined		Mean dias. range from
* Skylights	Not examined		Rule length
* Companionways	Not examined		Mooring ropes
* Hatchways	Not examined		
* Ventilators	Not examined		

Other items: /

\* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

30m,2,64 (MADE AND PRINTED IN ENGLAND)

LIVERPOOL

-3 AUG 1965

0132 12

© 2021

Surveyor to Lloyd's Register of Shipping

J. D. Sutherst.



HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold		F.P. tank		
"	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
"	'Tween decks				
No. 3	Hold		O.F. bunkers		
"	'Tween decks				
No. 4	Hold				
"	'Tween decks		Settling tanks		
No. 5	Hold				
"	'Tween decks		Deep tanks		
No. 6	Hold		Side tanks		
"	'Tween decks				
			Wing tanks		
	Cargo battens				
	Ceiling, etc.		Other tanks:		



© 2021

Lloyd's Register  
Foundation