

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex 22nd November, 1962
Overseas: Committee, London, E.C.3

Telephone: ROYAL 9166
Telex No.: 24305

Your ref: TECHNICAL/RB
2124.

R.
NAB/MRN

Dear Sirs,

M.S. "KING DAVID"

I acknowledge your letter of the 19th November, the contents of which have been noted, and would inform you that this vessel's class is subject to shell plate C.1 (port and starboard) being specially examined at the next Drydocking, to wasted upper deck plating in saloon accommodation being specially examined and dealt with as necessary at the Special Survey, to leaky bottom shell plating in way of No.3 D.B. tank suction pipe (starboard side) and to the temporary repaired propeller being specially examined at the next drydocking.

The Survey position is as follows :-

Special Survey due 4.63.

Auxiliary Boiler Survey due 6.63,

Screwshaft Survey due 12.63.

Steampipe Survey due 12.66.

Last examined in drydocking 11.61.

Yours faithfully,

Clerk to the
Classification Committee

Messrs. Cayzer, Irvine & Co., Ltd,
Cayzer House,
2/4, St. Mary, Axe, E.C.3.

© 2021

Lloyd's Register
Foundation

015474-015482-0035