

(Received at London Office)

FRI: 25 NOV 1898

No. 16574

# REPORT of SURVEY for REPAIRS, &c.

When handed in at Local Office 18 Port of Glasgow  
 Survey held at Glasgow Date, First Survey 7<sup>th</sup> Nov<sup>r</sup> East Survey 16 Nov<sup>r</sup> 1898  
 on the ~~Wood, Iron or Steel~~ S. S. Suddick Master Clark

TONNAGE:— Built at Warrington By whom J. Williamson & Sons When 1898 10  
 Owners Aberdeen Newcastle & Hull S. L. L. Port belonging to Aberdeen  
 Owners' Address \_\_\_\_\_

Surveyed Afloat or in Dry Dock? by Name of Dock for an Destined Voyage Coasting  
 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

B=CellDBorDBa feet; uE&B feet; I feet;  
 tonal capacity tons; FPT tons; APT tons; MT feet tons.

CHARACTER.	Year Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
* for Special Survey, Date of last Survey and of Periodical Surveys.		
<u>+ 100 A. 1</u>		
<u>contemplated</u>		

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Repairs, or Examination as per Rule, for completion in Secretary's letter

The Engine & Boiler openings have been efficiently closed up. Vessel has been placed in dry dock, the bottom examined and found to be in good condition

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Inner Bottom Plating	Inner Bottom Plating	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
State if Tanks now tested	State if Tanks now tested	Scuppers	Condition, how ascertained
Bulkheads	Bulkheads	Cargo Hatchways	(State if wedges removed)
Ceiling	Ceiling	Hatches	Sails
Cement or Asphalt (State which.)	Cement or Asphalt (State which.)	Planking of Wood Vessels	Equipment letter
Rudder	Rudder	Treenails ditto	Anchors, No. of
Windlass	Windlass	Breasthooks & Stems ditto	Cables (State if now ranged)
Have Pumps now been examined and found efficient?	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length (on board) size
Have Sluice Valves now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" Rule length (per Table 22) size
Have Watertight Doors now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawsers & Warps
Dblng. Plates under Sounding Pipes	Dblng. Plates under Sounding Pipes	Stringers, Clamps & Shelves ditto	Standing & Running Rigging
		Salting (State if examined.) ditto	
		Copper, or Y.M. (State if on Felt.) ditto	
		When put on, Month Year	

General Observations, Opinion as to Class, Recommendation, &c.:—  
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

The survey of this vessel is now completed, and the above is sent for the information of the Committee

Fee (if chargeable) per Scale II., Sec. 27	Fees applied for,
Survey Fee (per Section 28)	18
Damage or Repair Fee (if any) (per Sec. 28.)	
Printing Expenses (if chargeable)	18
Surveyor's Fee (if any)	

Received by me, H. Bond  
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute  
 Character assigned

FRI. 25 NOV 1898

