

"S. S. Crumley"

It is submitted the Barry Surveyors should be requested to supply a sketch of the engine seating showing the position of the started riveting. They should state whether the started riveting is due to bad workmanship or to whatever cause. They should also show upon the sketch the additions to the seating which they propose to make

Dr. 17.5.04
Ans'd 18th

J.P.L. L.S. 18/5/04
J.M.

© 2021

Lloyd's Register
Foundation