

REPORT of SURVEY for REPAIRS.

No. 206 Survey held at London Date Oct 10. 11. 18. 23. 1839
on the Bark Pestonjee Bomanjee Master M Hill
Tonnage 595 Built at Dumbarton When built 1835
By whom built _____ Owners Waddell & Co 23 Soles
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Messrs Hetchers Dry Dock

Blyde 107.
Original Survey, No. 2586, 413 Dated 1838 Classed 12. A 1
Port London

Repairs At the present time in consequence of damage - Stuffed
caulked Keel up - Hung - Cutwater & Head Rails & Sheets
refitted - 5 pair Iron Hanging knees to lower deck & a
cutch abaft - Recoppered on paper to the water

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Mizen Mast out</u>
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1839</u>	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

In my opinion this ship is in an efficient
state to remain as classed 12 A 1

George Bayley

The Amount of Fee.....£ 3 : 3 : is received by me, H

Committee's Minute 1 Nov 1839

Character assigned 12 A 1 and Surveyed