

REPORT of SURVEY for REPAIRS.

6304

No. _____ Survey held at London Date April 23 1840
 on the By Tyra Master B Swan
 Tonnage 213 Built at Greenwich When built 1839
 By whom built _____ Owners Sutcliffe & Co
 Port belonging to Greenwich Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock in Hawks Dry Dock

Original Survey, No. 674 Dated 1839 Classed A 1
 Port of London

Repairs *At the present time in consequence of having been on shore
 Bottom stripped, the started treenails driven ^{out} & replaced
 hung and caulked from the keel to the plates
 and the coppered over paper
Copper*

The Surveyor is also required to state the present Condition of the

Decks _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Spirketting _____ Plank Shears _____ Waterways _____ Hatchway Comings _____ Breasthooks _____	Transoms _____ Timbers of the Frame _____ Topsides _____ Wales _____ Counter _____ Plank & Treenails (Outside to the Water's Edge) Rudder _____ Copper _____	Windlass _____ Capstan _____ Pumps _____ Masts, Yards, &c. _____ Sails _____ Cables _____ Anchors No. of _____ Standing & Running Rigging _____
--	--	--

General Observations and Opinion, *It is in a very efficient state both in the Hull & Struts
 as required by the Instructions, and may retain her present Character*

[Signature]

The Amount of Fee.....£ 1 : 1 : 0 is received by me,

Committee's Minute 24th April 1840

Character assigned A 1 used & described *[Signature]*

