

ANNUAL SURVEYS.

7213

No. 300 Survey held at London Date Jan. 30th 1841
 on the brig William Swan Master Patten
 Tonnage 152 Built at Greenwich When built 1839
 By whom built _____ Owners Swan & Co.
 Port belonging to Greenwich Destined Voyage Calcutta
 Surveyed at in Dry Dock Messrs Dowsons

Original Survey, No. 417 Port of Clyde Classed 1A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings <u>in good</u>	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides <u>good</u>	Sails <u>good & efficient</u>
Plank Shears <u>in condition</u>	Wales <u>good</u>	Cables <u>efficient</u>
Waterways	Plank and Treennails <small>(Outside to the Water's Edge.)</small>	Anchor No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions,
At the present time, Shippers call the vessel the Helen and sheathed with yellow metal on paper - the ship is in a very efficient state and may

Committee Minute 10th Dec 1841
 Character assigned 10 A 1 *See note of check*

No. 310 Survey held at London Date Jan. 30th 1841
 on the brig Globe Master Hopper
 Tonnage 350 Built at Swansea When built 1836
 By whom built _____ Owners Allen
 Port belonging to _____ Destined Voyage Sydney
 Surveyed at in Dry Dock Messrs Dowsons

Original Survey, No. _____ Port of _____ Classed 1A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides <u>good when seen</u>	Sails <u>good & efficient</u>
Plank Shears	Wales <u>seen</u>	Cables <u>efficient</u>
Waterways	Plank and Treennails <small>(Outside to the Water's Edge.)</small>	Anchor No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions,
At the present time repairs to the upper, the ship is in good condition and may remain as shipped

Committee Minute _____ 1841
 Character assigned _____



© 2019
 Lloyd's Register
 Foundation