

# REPORT of SURVEY for REPAIRS.

Change of Property

No. 9337 Survey held at London Date Decr 1842 <sup>4</sup> 1843  
 on the Ship "Farnate" Master Drymer  
 Tonnage 488 Built at Greenock When built 1837  
 By whom built 376 Scott Owners Jayram  
 Port belonging to London Destined Voyage India  
 If Surveyed Afloat or in Dry Dock afloat & Dry Dock

Original Survey, No. \_\_\_\_\_ Dated \_\_\_\_\_ Classed 12 A1

Port \_\_\_\_\_

## REPAIRS

At the present time shipped upper course shrouds with hoove, and shrouds with yellow metal - the the lower deck now extended quite fore and aft caulked from the keel up -

### Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>"</u>	Capstan <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>"</u>	Pumps <u>"</u>
Spirkettling <u>Good</u>	Wales <u>"</u>	Masts, Yards, &c. <u>Insufficient</u>
Plank Shears <u>"</u>	Counter <u>"</u>	Sails <u>"</u>
Waterways <u>"</u>	Plank and Treenails (Outside to the Water's Edge) <u>"</u>	Cables <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of <u>"</u>
Breasthooks <u>"</u>	Copper <u>Yellow Metal 1843</u>	Standing & Running Rigging <u>"</u>

General Observations and Opinion, Is in the most efficient condition and may remain as Clapsen

The Amount of Fee.....£ : : is received by me,

Committee's Minute \_\_\_\_\_ 18

Character assigned \_\_\_\_\_

J. Heaviside Esq



© 2019

Lloyd's Register Foundation

2540-114-0425