

REPORT of SURVEY for REPAIRS.

28986

No. in Reg. Book. **No.** 232 Survey held at London Date Aug 22nd to Sep^r 12th 1867
 on the Ship "Isabella Mercus" Master L. T. Gillan
 Tonnage 569 Built at Ardrossan When built 1847
 By whom built _____ Owners Bremner
 Port belonging to London Destined Voyage Bermuda
 If Surveyed Afloat or in Dry Dock Union Dry Dock & Off Deptford

Last Survey, No. 19450 Port Liverpool Classed 13 A. 1. 6, 65
 REPAIRS now done Cont 60. 931.

The Yellow Metal stripped, hung in shores forward, two fore hoods of Garboard, of Eng Elm, worked on to the Stern, and new dove-tail plates fitted; - a pair of hanging knees added to lower deck beam forward, and two 1/4 Yellow Metal bolts driven in the upper part of the Stern-post through transom; three planks of upper deck on each side renewed with Yellow Pine, and the bottom caulked and resheathed with Yellow Metal upon Felt -

"Windlass mending and linings removed"
per Liverpool report No 19450

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	good
Comings	good	Transoms, Pointers, and Crutches	good	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	where	Ditto Ditto at other places	where	Condition, how ascertained	where
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of 3 B 1 S 2 K	
Topsides	seen	Ceiling	seen	Cables	seen
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter	caulked	Copper F & Y M When put on now		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	good where tested		

She is now in good condition, fit in our opinion to remain as classed A. 1.

The Amount of Fee.....£ : - : is received by me,

Special..... 1 : 1 : } @

Certificate (if required) _____

Committee's Minute 25 February 1868

Character assigned Cont 9 A 1

record M. W. S.



© 2019

Lloyd's Register Foundation
 LON653-0066