

REPORT of SURVEY for REPAIRS, &c.

No. 41740
No. in Survey held at London Date, first Survey 29th April Last Survey 5th May 1882
Reg. Book. on the Iron S.W. Sr. "Fanny" (Received at London Office, Friday, 19th May, 1882)

Master J. Holmes.
TONNAGE under Tonnage Deck 258
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 308
Crew Space, as per Rule
Register Tonnage, out on Beam
Engine Room
Reg. Tons as St^rmer, out on Bm. 192
Built at Glasgow
Owners J. Burnett & Co.
Residence
By whom built A & J. Inglis.
When built 1878
Port belonging to London
Destined Voyage Rouen.
If Surveyed Afloat or in Dry Dock In the Fountain Dry Dock.
(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
Last Survey, No. 28742 Port Lrd
REPAIRS, OR EXAMINATION AS PER RULE
Cause of Repairs to be clearly stated.
Classed 100 A.1.
11.80


Special Survey No. 1

This vessel has been placed in dry dock; the bottom examined and coated. The timber boards and ceiling equal to one stroke fore and aft each side removed; the cement examined and found adhering well to the iron; the masts and spars examined and all other requirements of the Rules complied with. One plate on the starboard side forward, in the first stroke below the sheerstroke renewed. The holds cleaned & painted. Eight planks of the Raised Quarter Deck renewed. The fore topmast renewed.

Present Condition of the		Freenails		Rivets		Steam winches	
Decks	good	Breasthooks and Stenson	good	Windlass and Capstan	good	Pumps	good
Waterways	Do	Transoms, Pointers, and Crutches	Do	Boats	Do	Masts, Yards, &c.	Do
Comings	Do	Timbers of the Frames at the openings	Do	Condition, how ascertained by examination	Do	Sails	good
Upper Deck Beams & Fastenings	Do	Ditto Ditto at other places	Do	Anchors No. of 2 B. 15. 1K	Do	Cables	complete
Lower Deck Beams & Fastenings	Do	Keelsons	Do	Hawsers and Warps	good	Standing & Running Rigging	Do
Planksheers	Do	Clamps and Shells	Do	Cargo and Main Hatchways	good	Hatches	good
Sheerstrakes	Do	Ceiling	Do	General Observations, Opinion as to Class, &c.	Do		
Topsides	Do	Rudder	Do				
Wales	Do	Copper (or P.M.)	When put on				
Plating	Do	Caulking of					
Plank (Bottom) and Counter	Do	Bottom, Deck, & Waterways	good				

The Amount of Entry Fee ... £ 4 : 4 : received by me, J. H. E.
19/9/82 Special ... £ 4 : 4 : 28.9.1882
Certificate (if required) to be sent as per margin... £ 5 :
(Travelling Expenses, if any, £)
Committee's Minute Tuesday, 19th September, 18 82.
Character assigned 100 A.1.
S.S. No. 1 82

J. A. Truscott.
Surveyor to Lloyd's Register of British and Foreign Shipping.



[Form No. 2 for Repairs, 4,000-7/2/82.]
(The Surveyors are requested not to write on or below the space for Committee's Minutes)

LONDON 669-0026