

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office) **UES. 11 OCT 1898**

Date of writing Report **10 Oct 98** When handed in at Local Office **10 Oct 98** Port of **London**

No. in Reg. Book. **400** Survey held at **London** Date, First Survey **23 Sept 98** Last Survey **5 Oct 98** (No. of Visits **4**)

400 on the Machinery of the **Wood, Iron or Steel** **J. J. Golfer** Master **Miller**

Tonnage { Gross **377** Net **189** Vessel built at **Aberdeen** By whom **J. Duttai & Co.** When **1891** 10

Registered Horse Power **60** Engines made at **Wm. & A. Rankine** When **'91** Boilers, when made (Main) **'91** (Donkey) **'91**

No. of Main Boilers **1** Owners **Temple & Co. Ltd** Port **London** Voyage

No. of Donkey Boilers **1** If Surveyed Afloat or in Dry Dock **In Hard off** Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Steam Pressure **160 lb** (State name of Dock.) **Stewart's works.**

in Main Boilers **80** in Donkey Boilers **80**

Last Survey No. **59936** Port **Lon**

Particulars of Examination and Repairs (if any) **Damage +100 A.I. 5-98 +L.M.C. 6-95**

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? **No.**

Do. " Donkey " **No.**

If this was not done, state for what reasons? **Boiler Survey not due.**

And what parts of the Boilers could not be thus thoroughly examined? **-**

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? **-**

Did the Surveyor examine the Safety Valves of the Main Boiler? **No** To what pressure were they afterwards adjusted under steam? **No-paj**

Did the Surveyor examine the Safety Valves of Donkey Boiler? **No** To what pressure were they afterwards adjusted under steam? **10**

Has the propeller shaft been drawn and examined at this time? **yes.** If spare propeller shaft fitted, state whether new? **yes.** **new.**

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? **new Bush**

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? **Complete.**

Now done on account of damage please see copy of Damage Report-Attached:-

Tail Shaft drawn and found fractured. Stern-bush found worn and defective.

Damage Repairs:- a new Stern-bush and a new Propeller shaft-fitted.

Please see City Forging Report-attached.

General Observations, Opinion, and Recommendation :-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or L.M.C. 9,97, 110 lbs F.D., &c.)

The Machinery of this vessel is in good order. So far as seen and in my opinion, is eligible to remain as classed. Without fresh record.

Office or Registration Fee (per Sec. 27) £ **2 2 0** Fees applied for **11/10 98/901**

Survey Fee per Section 28) £ **4 0**

Special Damage Fee (per Section 28) £ **1 18 0** Received by me **D. Atcham**

Travelling Expenses (if chargeable) £ **1 18 0** 16/10/98


State if Certificate is required

Committee's Minute **As noted**

Assigned


FRI. 14 OCT 1898

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Leeward shaft found fractured stem
bush worn & defective (due to damage
the propeller striking hard substance)
both now renewed

It is submitted that
this vessel is eligible to
remain as CLASSED.


11/10/08

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation