

A new propeller shaft fitted at bronze.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Slight repairs to boilers & machinery
overhauled on account of damage

It is submitted that

this vessel is eligible for

THE RECORD. + LMC 12.98

B.S. 11.99.

EMRD.
17/11/99.

* THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

© 2019



Lloyd's Register
Foundation