

side stringer plate in way of the after mast to deal with - Permanent repairs (ss.) No.2 hold and (p.s.) No.3 to carry out at first dry-docking.

Hause pipes wasted at out part to deal with - Holds and bilges to coat.

T. Reed & W. Money

Surveyors to Lloyds Register



© 2019

Lloyd's Register
Foundation

COPY



© 2019

Lloyd's Register
Foundation