

Gross Tonnage 601.8
Register Tonnage 128.23

of beam at side of uppermost continuous deck. See Sec. 3 (1c) } D 14.76
1st Longitudinal Number (L x D)..... = 2181

Owners Government
Managers ✓

5c.7.28.

W/1006

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME St S "BOMBO"

Rpt. Lth No. 17761

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

1st Long

Transverse No. 2181

Depth "d" 11.75

Framing: Table No. ✓

Description Bull angle frames

2nd Longitudinal No. 6801

Proportions Length 10.9
Depth =

~~Deck~~ Sheerstrake

.50, approved .40.

Shell unbleached 25% (unes)

Revised Rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel).

10th (Stl).

Cell D.B. 80' 116t, F.P.T. 35t, A.P.T. 6t.

F.K, H.B.H, pt cem pt asp, Lloyds A.C.P.

Q 49', B 18', F 22'.

machy aft.

The Certificate of Classification to be endorsed "Cargo buttons not fitted" and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register
Foundation

W1006-0001

Roop Deck, Angle, L or L

Spacing.....

Bridge Deck, Angle, E or F

DOUBLE BOTTOM.

Solid Floors, thickness and spacing

29 every frame

45 3 3