

2m, 10.48.

REEBOARD REPORT on the


Magdalena

n C.11  
beams

It is submitted the Belfast Lawyers be advised  
that the arrangements as reported on C.11 are in  
order but they should report the bearing surface  
of ~~both~~ beams for Nos 1-4 Lutes on Bridge & Promenade  
Docks.

It is further submitted that out & when be forwarded  
for issue when ON & GRT are inserted thereon.

5  
why



Ed  
© 2020  
31-12-2019

Lloyd's Register  
Foundation