



Lloyd's Register of Shipping

1.47 HMC
44 MS
TS CL
filled
d) as }
rified }
ries of
ave been
copy of w
ating not
oredeck p
way of wa
recommen
t permit t
Y.M.
on Feb.)
Month
&c.
ow ascertained
(wedges removed.)
tter
of
ate if now ranged)
length
(on board)
Rule length
Locker
ers & Warps

of Surveyors.....

Received from Chief Surveyors.....

S NAME SEWALLS POINT.

REPORT Bal. No. 8678

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24 / 5 / 92.)

Survey.....

Repairs - S. R. L.

When due.....


Noted:

Subject to fractured & buckled stem & poop deck plating, to shell plating etc. (S.S.), and to deck plating in way of Kingposts (F.S.F.) and foremast being dealt with and the S.S. bung carried out before 12.48 and to No. 7. Hatch cover from forward being renewed on vessels return to Baltimore.

CBM.
13-9-48

Cargo battens not fitted.

© 2020



W1029-0098

Lloyd's Register
Foundation