

DISCLOSED

PAY No

on the ~~Wood-Tenue~~ Steel Twin Se. 4Mst. "DON JOSE"

TONNAGE	10893	Built at	Wesermunde-G	By whom	J. C. Tecklenborg A.G.	When	1920
GROSS	10044	Owners	Madrigal & Co.	Owners' Address	(if not already recorded in Appendix to Register Book).		
UNDER DEK	6791	Managers	-	Port belonging to	Manila, P.I.		
NET							

Surveyed Afloat or in Dry Dock?		Dry	Name of Dock		Talkoo	Destined Voyage																																																																																																					
WB=CellDBorDBa	feet;	uE&B	feet;	f	feet	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)																																																																																																					
total capacity	tons.	FPT	tons;	APT	tons;	MT	feet																																																																																																				
<p>N.B.—All alterations in the existing records should be underlined.</p> <table border="1"> <thead> <tr> <th>CHARACTER.</th> <th>1st and 2nd</th> <th>3rd</th> <th>4th</th> <th>5th</th> <th>6th</th> <th>7th</th> <th>8th</th> <th>9th</th> <th>10th</th> <th>11th</th> <th>12th</th> <th>13th</th> <th>14th</th> <th>15th</th> <th>16th</th> <th>17th</th> <th>18th</th> <th>19th</th> <th>20th</th> <th>21st</th> <th>22nd</th> <th>23rd</th> <th>24th</th> <th>25th</th> <th>26th</th> <th>27th</th> <th>28th</th> <th>29th</th> <th>30th</th> <th>31st</th> <th>32nd</th> <th>33rd</th> <th>34th</th> <th>35th</th> <th>36th</th> <th>37th</th> <th>38th</th> <th>39th</th> <th>40th</th> <th>41st</th> <th>42nd</th> <th>43rd</th> <th>44th</th> <th>45th</th> <th>46th</th> <th>47th</th> <th>48th</th> <th>49th</th> <th>50th</th> <th>51st</th> <th>52nd</th> <th>53rd</th> <th>54th</th> <th>55th</th> <th>56th</th> <th>57th</th> <th>58th</th> <th>59th</th> <th>60th</th> <th>61st</th> <th>62nd</th> <th>63rd</th> <th>64th</th> <th>65th</th> <th>66th</th> <th>67th</th> <th>68th</th> <th>69th</th> <th>70th</th> <th>71st</th> <th>72nd</th> <th>73rd</th> <th>74th</th> <th>75th</th> <th>76th</th> <th>77th</th> <th>78th</th> <th>79th</th> <th>80th</th> <th>81st</th> <th>82nd</th> <th>83rd</th> <th>84th</th> <th>85th</th> <th>86th</th> <th>87th</th> <th>88th</th> <th>89th</th> <th>90th</th> <th>91st</th> <th>92nd</th> <th>93rd</th> <th>94th</th> <th>95th</th> <th>96th</th> <th>97th</th> <th>98th</th> <th>99th</th> <th>100th</th> </tr> </thead></table>								CHARACTER.	1st and 2nd	3rd	4th	5th	6th	7th	8th	9th	10th	11th	12th	13th	14th	15th	16th	17th	18th	19th	20th	21st	22nd	23rd	24th	25th	26th	27th	28th	29th	30th	31st	32nd	33rd	34th	35th	36th	37th	38th	39th	40th	41st	42nd	43rd	44th	45th	46th	47th	48th	49th	50th	51st	52nd	53rd	54th	55th	56th	57th	58th	59th	60th	61st	62nd	63rd	64th	65th	66th	67th	68th	69th	70th	71st	72nd	73rd	74th	75th	76th	77th	78th	79th	80th	81st	82nd	83rd	84th	85th	86th	87th	88th	89th	90th	91st	92nd	93rd	94th	95th	96th	97th	98th	99th	100th
CHARACTER.	1st and 2nd	3rd	4th	5th	6th	7th	8th	9th	10th	11th	12th	13th	14th	15th	16th	17th	18th	19th	20th	21st	22nd	23rd	24th	25th	26th	27th	28th	29th	30th	31st	32nd	33rd	34th	35th	36th	37th	38th	39th	40th	41st	42nd	43rd	44th	45th	46th	47th	48th	49th	50th	51st	52nd	53rd	54th	55th	56th	57th	58th	59th	60th	61st	62nd	63rd	64th	65th	66th	67th	68th	69th	70th	71st	72nd	73rd	74th	75th	76th	77th	78th	79th	80th	81st	82nd	83rd	84th	85th	86th	87th	88th	89th	90th	91st	92nd	93rd	94th	95th	96th	97th	98th	99th	100th								

Last Report, No. 4768. Port Shi.

(Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as
 painted on Ship and now verified } 10 ft 5 1/2 in.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR **Part Special Survey 2nd.No.1, Annual Freeboard Survey and Examination for Manila Customs.**

PART S.S.N. 1 NOW DONE.

Vessel placed in dry dock, bottom, rudder, keel, stem, stern frame & propeller brackets cleaned, examined and placed in good condition and recoated.

Anchors, chain cables ranged, cables wire brushed and cleaned for inspection and gauging and found in good condition, cables deped with fuel oil before replacing.

Chain locker, hawse pipes and cable compressors examined and placed in good condition.

Decks, masts, spars & rigging, hatchways, hatches in position at the hatchways, ventilators, casings, coamings, plating in way of side lights, general equipment, rudder quadrant & tiller, steering gear & its connections, examined & found or placed in good condition. (Continued overleaf

(Continued overleaf

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Replaced in place								

PRESENT CONDITION OF THE

Decks	Good	State if Tanks have been examined inside	Yes, as stated	Air and Sounding Pipes	8	Copper, or Y.M. of Wood Vessels	-
Caulking of Decks	"	State if Tanks now tested	Yes, as stated	Dblg. Plates under Sounding Pipes		(State if on Felt.)	-
Coamings	"	Bulkheads	Part seen Good	Engine Room Skylights	Good	When put on, Month	- Year -
Beams & Fastenings	"	Ceiling	" " "	Coal Bunkers, Open'gs, Lids, &c.	"	Boats	Good
Outside Plating	"	Cement or Asphalt	-	Oil Bunkers	-	Masts, Yards, &c.	-
" " in way of sidelights	"	(State which.)	Good	Scuppers	Good	Condition, how ascertained	-
Breasthooks	-	Rudder	"	Cargo Hatchways	"	(State if wedges removed)	-
Transoms	-	Steering gear and its connections	X " X	Hatches	"	Sails	-
Frames	Part seen Good	Windlass	"	Planking of Wood Vessels	-	Equipment letter	gt
Reverse Frames	" " "	Have pumps now been examined and found efficient?	No	Caulking ditto	-	Anchors, No. of	3B 1S 1K
Longitudinals	-	Have Sluice Valves now been examined and found efficient?	No	Treenails ditto	-	Chain Locker	Yes
Transverses	-	Have Watertight Doors now been examined and found efficient?	Yes	Breasthooks & Stemson ditto	-	Cables (State if now ranged)	Yes
Floors	Part seen Good	Have Ventilators and their Coamings been examined and found efficient?	Yes	Transoms Pointers, & Crutches ditto	-	" length mean diamr.	See overleaf
Keelsons	" " "			Timbers of Frame at openings ditto	-	(on board)	2, 11/2
Stringers	" " "			Ditto Ditto at other places ditto	-	" Rule length	330 size
Inner Bottom Plating	" " "			Stringers, Clamps & Shelves ditto	-	Hawser & Warps	Good
				Salting ditto	-	Standing and Running Rigging	"
				(State if examined.)			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24.

This vessel, as far as seen, is in good and efficient condition and eligible, in my opinion, to remain as classed and to have record of survey 8-41. and notation S.S.No.1 with date when survey completed.

Survey Fee (per Section 20)	\$215.00:	:	Fees applied for,
Annual Freeboard	\$100.00:	:	12/8/41
Special Damage or Repair Fee (if any)	£	:	
(per Marilla Customs	\$100.00:	:	Received by me,
Travelling Expenses (if chargeable)	\$ 35.00:	:	19.....
10-8-41 Sunday fee	\$ 80.00:	:	
Second Surveyor's Fee (if any)	£	:	

Fees applied for,
12/8/41

Received by me,

Surveyor to Lloyd's Register of Shipping

FRI 18 SEP 1942

Committee's Minute

FRI. 14 NOV 1941

Character Assigned

10041
Aron. Sh. w/ft 8
Fitt. for all fuel
m (Deferred)

No later
Survey reported

W1049-0028

Nos. 1 & 9 double bottom tanks tested.

Nos.1 & 7 lower holds & tween decks, Nos.2,3,4, & 5 upper & lower tween decks, No.6 upper tween decks, bridge space, engine & boiler spaces, examined and placed in good condition.

Derricks tested.
Watertight door tried and found satisfactory.
Air tanks of life boats tested.

Fittings and appliances for the protection of openings, guard rails, freeing ports and means of access to crews quarters examined and found in good order.

Closing appliances as per Load Line Certificate checked, freeboard verified and found in order. Survey form and verification form sent to New York. Certificate endorsed.

TO COMPLETE S.S.No.1.

Nos. 2, 3, 4, 7 & 8 double bottoms to be examined internally and tested. ✓ Nos. 5 & 6 double bottom tanks to be tested?

Nos. 2, 3, 4, 5 & 6 lower holds and masts & rigging to be examined.

REPAIRS:-Wear & Tear.

50 Hatch cleats renewed.

<u>Chain Cables</u>	135 fathoms	2, 11/16"
	75 "	2, 3/4 ✓
	90 "	2, 13/16
	30 "	2, 7/8
	<u>330.</u> ✓	"

Testing of FP & AP tanks? Have poop & forecabin spaces been examined? Windlass, pumps, air & sounding pipe with doubling plates examined?

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

TUES. 22 FEB 1944

OMIT CLASS
ON RE-PRINT

© 2020

Lloyd's Register
Foundation