

*Urgent
wire*

m.v. "MODAVIA". No.29421 in Register Book.

Messrs. Vickers Ltd. - No.626.

The vessel was built to class with this Society in April of this year.

The Barrow Surveyors now state that No.5 crankpin of the solid forged crankshaft has developed a flaw and it is proposed to cut out this pin together with the crank webs and fit a new crank pin and webs forged in one piece and shrunk on to the journals.

A plan showing the details of the proposed repair has been forwarded.

The scantlings of the new parts meet the requirements of the Rules.

IT IS SUBMITTED the Barrow Surveyors be informed by wire that the proposed method of repairing No.5 crank of these engines, as shown on the plan, could be accepted.

Return plan.

29.12.27.

Tele. 29/12/27



© 2021

Lloyd's Register
Foundation

W106-0209