

I have to report that the Freeboard from the centre of disc to the top of the

3m, 225.

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stk. T.S.S. LLANDOVERY CASTLE Report Gls No. 45020

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey 1<sup>st</sup> Entry When due \_\_\_\_\_ Revised Rules \_\_\_\_\_

✦ 100 A.I. (Steel) "with freeboard"  
3 dks (atl - weather dk pt teaks.). 4<sup>th</sup> dk (Stl) in No 1 & 2 holds.  
Cell D.B a.v E 168', f 188' 1237t, F.P.T. 116t, A.P.T. 140t  
F.K, 8B.H, pt Cem, Lloyd's A.C.P.  
B 212', F 66'.



8  
D. 10. 25

Is fee paid?

Form for Certificate

W1091-0049