

MENTS.

Inquire that the decks would be repaired at New York. Their represent

Im. 12. 10. H.

2

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl. s.s. "CAXAMBU".

Report N. Yk. No 26826

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 245/92.)

2nd No. 2

SURVEY PARTLY HELD. *Temporary repairs*

When due 6-26

When proposed to be completed *Must be carried out on arrival at Rio Secys letter 22.10.76*

Portion of Survey held, &c.,

To complete survey repairs see Rio Rpt-1613 9.11.76 76876.

Shell plating at bulge repaired by EW 2.30 to be specially examined at next dry docking.

Sumner 5.11.76



W1096-0138

subject to decks etc. being repaired upon arrival at Rio de Janeiro